



Recommended Soldering Conditions

Flow Soldering

Hand Soldering

Solder iron temperature: 350±5

Heating time: 3 seconds max

General attention

High soldering temperatures and long soldering times can cause leaching of the terminat

on the component. High soldering times can cause a decrease in adhe

**Spark Gap
GS26DIP Series**